Compliance plan for Arc Innovations

Non-compliance	Description			
Audit Ref: 4.10	Information updated in the registry later than 10BD			
With: 3 of Schedule	Potential impact: Low			
11.4	Actual impact: Low	Actual impact: Low		
	Audit history: Multiple times			
From: 16-Jul-17	Controls: Moderate			
To: 30-Apr-17	Breach risk rating: 2			
Audit risk rating	Rationale for	r audit risk ratin	g	
Low	The controls are rated as moderate because there are some improvements that can be made to them to achieve compliance. The impact on settlement is potentially minor, therefore audit risk rating is low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Arcs overall compliance is very good in this area, the majority of late updates is due to backdating of corrections. We will continue with this as it makes the information in the registry more accurate.		Ongoing	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
The bug in the Vanilla job manager (VJM) database relates to the system picking up the previous site certificate date and entering that as the asset removal date. As there are very few of these occurring now (we do not provide removal dates as the Registry does this on a new MEP update) we will switch off the automated process and deal with each on a case by case basis to ensure a correct date is used. This will continue to diminish over the next few years.		August 2018		

Non-compliance	Description		
Audit Ref: 6.1 With: 1(1) of	MEP nomination acceptance for one ICP was backdated to 17/08/13 as a part of clean-up process		
Schedule 11.4	Potential impact: None Actual impact: None		
From: Click here to enter a date.	Audit history: None		
To: 14-Mar-18	Controls: Strong Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are recorded as strong. Arc Innovations does not get many MEP nominations. They are checked daily and evaluated. No impact on settlement outcomes		
Actions taken to resolve the issue		Completion date	Remedial action status
ARCM do not accept any nominations, the above ICP was accepted by mistake and is a very rare event.		Cleared	Identified
Preventative actions taken to ensure no further issues		Completion	

will occur date
ARCS nomination acceptance is currently automated, we will look at our company policy on this to ensure we still accept nominations within the required timeframes when required or reject the nomination asap and request the retailer nominate NGCM.

Non-compliance	Description		
Audit Ref: 6.2 With: 7(1) of Schedule 11.4	Information for 8 ICPs is missing; some information for metering installations on Scanpower's network is incorrect (controls devices for 1,224 ICPs)		
	Potential impact: Low		
From: 16-Jul-17	Actual impact: Low		
To: 30-Apr-17	Audit history: Multiply times		
	Controls: Moderate		
	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are recorded as moderate. The impact on settlement is potentially minor, therefore audit risk rating is low. Meters on Scanpower's network will be replaced as part of an upgrade to smart meters		
Actions taken to resolve the issue		Completion date	Remedial action status
Data cleansing has reduced the ICPs with no information to 8 out of 113,000. These were gifted to Arc without correct information and efforts to gather this info have been unsuccessful. These will be upgraded when we clean up the interim certified meters in the Scanpower area.		September 2018	Identified
The 1,224 ICPs are mostly legacy metering, some expired interim certified which is due to be displaced. We will investigate the rest to try and identify what configuration is on site and gather the missing LCD info.			
Preventative actions taken to ensure no further issues will occur		Completion date	
Ongoing reconciliation between the registry and our systems will pick up any anomalies and these will be corrected. An investigation will be done to confirm these sites configuration and correct/gather further info if needed.		September 2018	

Non-compliance	Description		
Audit Ref: 6.3	There is not a process to comply fully with this clause.		
With: 6 of Schedule	6 of Schedule Potential impact: Low		
11.4	Actual impact: Low		
	Audit history: None		
From: 16-Jul-17	Controls: Moderate		
To: 30-Apr-17	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The impact on settlement is potentially small, therefore audit risk rating is low. In the past Arc Innovations put a lot of work into the clean-up of records in the registry.		
Actions taken to resolve the issue		Completion date	Remedial action status
New report being created to check reconcile the asset level information against the registry on a monthly basis. Focus will be on ensuring corrections are done within the timeframes allowed.		July 2018	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Escalate creation of new report, prioritization of resource to carry out reconciliation.		July 2018	

Non-compliance	Description		
Audit Ref: 7.1 With: 10.38(a)	Certification expired for 197 meteri 2 and 29 cat 1) Potential impact: Low	ng installation	n (168 cat
From: 16-Jul-17 To: 30-Apr-17	Actual impact: Low Audit history: Multiplier times Controls: Moderate		
Audit risk rating	Breach risk rating: 2 Rationale for audit risk rating		
Low	The controls are rated as moderate because there are some improvements that can be made to them to achieve compliance. The number of non-certified installations will possibly be increasing every year as a result of the deployment of the smart meters strategy in the past. It could have a minor impact on settlement outcomes if discovered that installations record incorrect volumes.		
Actions taken to resolve the issue		Completio n date	Remedia I action status

some componer initially installed expiry date from	nt's cer I. The A n the ol	tification da Arc system c Idest compo	however we are finding issues where ates were not correctly entered when lerives the installation certification onent in the system, if a component Il affect the date in the registry.	Nov 2018	ldentifie d
ICP	Mete r cat	Cert Exp date	Comments		
0005437890RN7B 6	1	01/01/2016	Ripple relay cert date is 1/01/2001?		
0005458722RN1B 6	1	01/01/2016	expiry date updated in Registry to 29/01/2023		
0005652642RN1D A	1	01/02/2018	Pre pay to post pay, new meter installed 2011 with cert date 1/02/2003?		
0005974232RNAF 1	1	01/01/2016	Second meter has cert date 1/01/2001?		
0006171613RN07 A	1	01/02/2018	Meter cert 1/02/2003? Installed in 2008?		
0006500889RN9A 1	1	26/07/2017	Pre pay to post pay in 2012, meter cert is 2002?		
0006601154RNFA 5	1	01/01/2016	Installed 2007, meter cert date 2001?		
0006639690RNA6 E	1	01/01/2016	expiry date updated in Registry to 23/05/2033		
0006748597RNBD 2	1	11/01/2018	expiry date updated in Registry to 17/05/2033		
0006799825RN11 C	1	01/01/2016	Installed 2008, one meter cert date 2001?		
0006830269RNE9F	1	01/01/2016	Ripple relay cert date 1/01/2001 yet replaced in 2018		
0007117773RN7A F	1	01/01/2016	Meter cert 2001, installed in 2007		
7012005000CHFA 0	1	04/12/2016	Registry showing metering category 9?		
incorrect in our	system	causing the	ssue where component dates are e installation expiry date to be earlier ted in bulk and this will flow through		
large number of certifications fal unable to keep u	^e meter ling du up and ertifica	s are expirin e over the r have theref tion back of	of Arc Cat 2 were deployed and a ng. Due to the high number of next 12 months, the ATH has been fore enlisted an additional technician n track. We expect they will have		
Preventative actions taken to ensure no further issues will occur			Completio n date		
Correct the data in our PSP system, this is a one off as we are not installing Cat 2 Arc metering anymore.			Nov 2018		
2018 is where most of the Arc Cat 2 certifications expire, once these are recertified things volumes will go back to normal.					

Non-compliance	Description			
Audit Ref: 7.19	2,202 ICPs with expired interim certification			
With: 18 of Schedule	Potential impact: Medium			
10.7	Actual impact: Medium			
	Audit history: None			
From: 16-Jul-17	Controls: Strong			
To: 30-Apr-18	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Medium	Controls are recorded as strong. Certification has been expired for 2,202 installations. Arc Innovations implemented a plan to rapidly reduce the number of such installations. In the period between our visit to Christchurch and submitting a draft report to Arc Innovations, 80 installations were recertified and NGCM is the new MEP. The impact on settlement outcomes is recorded as moderate because of the increased likelihood of inaccuracy of metering installations.			
Actions taken to resolve the issue		Completion date	Remedial ac status	tion
Vector AMS has an ongoing project to manage the recertification of its expired interim certified meters. The above 2,202 are bundled up in this project which is ongoing and has been well communicated to the Authority and other relevant parties. The majority of these are in the Scanpower and Centralines Networks.		Ongoing	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Continue to deploy new meters where possible. Work with Retailers to clear issues preventing upgrading ICP. Keep pressure on Retailers who are not allowing us access to recertify meters. Continue reporting status to the EA.		September 2020		

Non-compliance	Des	cription	
Audit Ref: 8.2	171 metering installations category 2 were not inspected.		
With: 46(1) of	Potential impact: Low		
Schedule 10.7	Actual impact: Low		
	Audit history: Once previously		
From: 16-Jul-16	Controls: Moderate		
To: 30-Apr-17	Breach risk rating: 2		
Audit risk rating	Rationale fo	r audit risk ratin	g
Low	The controls are rated as moderate because there are some improvements that can be made to them to achieve compliance. The number of non-certified has increased since the last audit. This could have a minor impact on settlement outcomes if discovered that installations record incorrect volumes.		
Actions taken to resolve the issue		Completion date	Remedial action status
Arc continues to improve its process to ensure the certification of its Cat 2 ICPs do not expire before being recertified. This is the most efficient outcome and will resolve two non-compliances.		Sept 2018	Identified
	g out 12 months in advance for nanaged closely within the team.		
A thorough review of the current process will be undertaken, and any improvements identified will be implemented. This should ensure recertification is completed within the certification period.			
Preventative actions taken to ensure no further issues will occur		Completion date	
Undertake a thorough review of the current process to identify why, even ICPs are taking so long to recertify, and put in measures to address these.		Sept 2018	