

## Report on market operation service providers' compliance

**December 2017**

This report includes:

- the publication<sup>1</sup> of the sections of the reports that relate to breaches of the Electricity Industry Participation Code (Code) by the pricing manager, received by the Authority in the previous calendar month
- the republication<sup>2</sup> of the sections of the reports that relate to breaches of the Code by the clearing manager, received by the Authority in the previous calendar month
- the republication<sup>3</sup> of the sections of the initial report that relate to breaches of the Code by the reconciliation manager, received by the Authority in the current calendar month
- the republication of the sections of the report that relate to breaches of the Code by the FTR manager, received by the Authority during the previous calendar month
- the republication of the sections of the report that relate to breaches of the Code by the registry manager, received by the Authority during the current calendar month
- the republication of sections of the report that relate to breaches of the Code by the system operator and the system operator's discretionary action, received by the Authority in the previous month.

---

<sup>1</sup> As required by clause 13.214 of the Code

<sup>2</sup> As required by clause 14.69 of the Code

<sup>3</sup> Clause 15.33 of the Code requires the Authority to publish the sections of the reports that relate to an alleged breach of the Code by the reconciliation manager by 1630 hours on the 2<sup>nd</sup> business day following the day on which the Authority receives the report. These reports are available at <http://www.ea.govt.nz/industry/market/statistics-reports/reconciliation-manager-monthly-breach-reports/>.

**Self-reported breaches by the pricing manager (under clause 13.213 of the Code)**

There were no self-reported breaches by the pricing manager.

**Self-reported breaches by the clearing manager (under clause 14.68 of the Code)**

There were no self-reported breaches by the clearing manager.

**Self-reported breaches by the reconciliation manager (under clause 15.30(1) of the Code)**

Note that this is a summary of the reconciliation manager monthly breach report which is published separately

There were no self-reported breaches by the reconciliation manager.

**Self-reported breaches by the FTR manager (Not required by the Code)**

There were no self-reported breaches by the FTR manager.

**Self-reported breaches by the registry manager (Not required by the Code)**

There were no self-reported breaches by the registry manager.

**Self-reported breaches by the system operator (under clause 3.14)**

One Code breach was reported. This related to the pricing error mentioned last month, concerning acceptance of dispatchable demand bids from WITS into the market system. Several complex circumstances came together at the same time, allowing the error to occur. The breach had a minor market impact.

**Discretionary action by the system operator (under clause 13.102)**

**Event Date & Time**

**Event Description**

8/11/2017 1:47:09 AM

COL0661 COL0. Clear COL-HOR violations Last Dispatched Mw: 39

8/11/2017 4:14:17 AM

COL0661 COL0. To resolve COL\_HOR violations <8 mins. Last Dispatched Mw: 39

8/11/2017 4:43:26 AM

COL0661 COL0. To resolve COL\_HOR violations <8 mins. Last Dispatched Mw: 35

9/11/2017 12:00:24 PM

MAN2201 MAN0. Return of Extended Potline 2. Last Dispatched Mw: 555

14/11/2017 12:02:33 PM

**Discretionary action by the system operator (*under clause 13.102*)**

MAN2201 MAN0. To provide room for Extended Potline Line 2 restoration now. Last Dispatched Mw: 738

14/11/2017 12:10:14 PM

MAN2201 MAN0. To provide room for Extended Potline Line 2 restoration now. Last Dispatched Mw: 555

14/11/2017 12:13:48 PM

MAN2201 MAN0. To provide room for Extended Potline Line 2 restoration now. Last Dispatched Mw: 625

20/11/2017 1:41:46 PM

MAN2201 MAN0. To allow restoration of TWI potline Last Dispatched Mw: 555

23/11/2017 11:58:09 AM

MAN2201 MAN0. Manage TWI reduction line 2 restoration Last Dispatched Mw: 333

23/11/2017 1:44:34 PM

WRK0331 TAA0. To manage dispatch following WRK T30 tripping.

27/11/2017 2:02:01 PM

MAN2201 MAN0. To allow restoration of TWI potline. Last Dispatched Mw: 444

30/11/2017 12:02:37 PM

MAN2201 MAN0. TWI extended reduction line offload, Line 2 Last Dispatched Mw: 333

This report was published by the Authority on 20 December 2017. For further inquiries please contact the Authority at the Electricity Authority or send an email to [marketoperations@ea.govt.nz](mailto:marketoperations@ea.govt.nz).