

Report on market operation service providers' compliance January 2018

This report includes:

- the publication of the sections of the reports that relate to breaches of the Electricity Industry Participation Code (Code) by the pricing manager, received by the Authority in the previous calendar month
- the republication² of the sections of the reports that relate to breaches of the Code by the clearing manager, received by the Authority in the previous calendar month
- the republication³ of the sections of the initial report that relate to breaches of the Code by the reconciliation manager, received by the Authority in the current calendar month
- the republication of the sections of the report that relate to breaches of the Code by the FTR manager, received by the Authority during the previous calendar month
- the republication of the sections of the report that relate to breaches of the Code by the registry manager, received by the Authority during the current calendar month
- the republication of sections of the report that relate to breaches of the Code by the system operator and the system operator's discretionary action, received by the Authority in the previous month.

As required by clause 13.214 of the Code

As required by clause 14.69 of the Code

Clause 15.33 of the Code requires the Authority to publish the sections of the reports that relate to an alleged breach of the Code by the reconciliation manager by 1630 hours on the 2nd business day following the day on which the Authority receives the report. These reports are available at http://www.ea.govt.nz/industry/market/statistics-reports/reconciliationmanager-monthly-breach-reports/.

Self-reported breaches by the pricing manager (under clause 13.213 of the Code)

There were two breaches of the Code by the pricing manager with respect to Clause 13.142(1).

On the 11 December 2017 the pricing manager incorrectly published prices as interim for trading date 10/12/2017 when they should have been published as provisional. When prices were published as interim there was an unresolved metering situation.

On the 24 December 2017 the pricing manager incorrectly published prices as interim for trading date 23/12/2017 when they should have been published as provisional. On this occasion when prices were published as interim there was an unresolved infeasibility situation.

Self-reported breaches by the clearing manager (under clause 14.68 of the Code)

There were no self-reported breaches by the clearing manager.

Self-reported breaches by the reconciliation manager *(under clause 15.30(1) of the Code)*Note that this is a summary of the reconciliation manager monthly breach report which is published separately

There were no self-reported breaches by the reconciliation manager.

Self-reported breaches by the FTR manager (Not required by the Code)

There were no self-reported breaches by the FTR manager.

Self-reported breaches by the registry manager (Not required by the Code)

There were no self-reported breaches by the registry manager.

Self-reported breaches by the system operator (under clause 3.14)

There were no self-reported breaches by the system operator.

Discretionary action by the system operator (under clause 13.102)

Event Date & Time Event Description

Discretionary action by the system operator (under clause 13.102)

4/12/2017 12:00:36 PM

BEN2202 BEN0. To allow restoration of TWI Potline.

4/12/2017 12:01:11 PM

MAN2201 MAN0. To allow restoration of TWI Potline.

6/12/2017 11:38:12 AM

MAN2201 MAN0. To allow restoration of TWI Potline.

7/12/2017 12:58:50 AM

MAN2201 MAN0. Emergency Potline.

20/12/2017 12:04:49 PM

MAN2201 MAN0. Extended Potline 2, 183MW.

This report was published by the Authority on 18 January 2018. For further inquiries please contact the Authority at the Electricity Authority or send an email to marketoperations@ea.govt.nz.