

Report on market operation service providers' compliance September 2018

This report includes:

- the publication of the sections of the reports that relate to breaches of the Electricity Industry Participation Code (Code) by the pricing manager, received by the Authority in the previous calendar month
- the republication² of the sections of the reports that relate to breaches of the Code by the clearing manager, received by the Authority in the previous calendar month
- the republication³ of the sections of the initial report that relate to breaches of the Code by the reconciliation manager, received by the Authority in the current calendar month
- the republication of the sections of the report that relate to breaches of the Code by the FTR manager, received by the Authority during the previous calendar month
- the republication of the sections of the report that relate to breaches of the Code by the registry manager, received by the Authority during the current calendar month
- the republication of sections of the report that relate to breaches of the Code by the system operator and the system operator's discretionary action, received by the Authority in the previous month.

Clause 15.33 of the Code requires the Authority to publish the sections of the reports that relate to an alleged breach of the Code by the reconciliation manager by 1630 hours on the 2nd business day following the day on which the Authority receives the report. These reports are available at http://www.ea.govt.nz/industry/market/statistics-reports/reconciliationmanager-monthly-breach-reports/.

1113712_1.docx

As required by clause 13.214 of the Code

As required by clause 14.69 of the Code

Self-reported breaches by the pricing manager (under clause 13.213 of the Code)

There were no self-reported breaches by the pricing manager.

Self-reported breaches by the clearing manager (under clause 14.68 of the Code)

There were no self-reported breaches by the clearing manager.

Self-reported breaches by the reconciliation manager (under clause 15.30(1) of the Code) Note that this is a summary of the reconciliation manager monthly breach report which is published separately

There were no self-reported breaches by the reconciliation manager.

Self-reported breaches by the FTR manager (Not required by the Code)

There were no self-reported breaches by the FTR manager.

Self-reported breaches by the registry manager (Not required by the Code)

There were no self-reported breaches by the registry manager.

Self-reported breaches by the system operator (under clause 3.14)

The system operator reported one breach of the Electricity Industry Participation Code 2010 in August. This related to the modelling of embedded generation at Cobb.

Discretionary action by the system operator (under clause 13.102)

Event Date & Time Event Description

1/08/2018 23:41

MAN2201 MAN0: Required for TWI potline 2 restoration

5/08/2018 23:46

MAN2201 MAN0: For TWI potline 2 restoration

6/08/2018 4:36

MAT1101 ANI0: ANI generation tripped

8/08/2018 21:36

MAT1101 MAT0: Tripping on KAW_T12

Discretionary action by the system operator (under clause 13.102)

8/08/2018 21:39

KAW1101 KAG0: Tripping on KAW_T12

8/08/2018 23:10

MAN2201 MAN0: Extended potline, Line 2

8/08/2018 23:46

MAT1101 MAT0: KAW_T12 tripping

12/08/2018 23:50

MAN2201 MAN0: Line 2 Offload restoration

15/08/2018 23:57

MAN2201 MAN0: Required for system security

19/08/2018 23:46

MAN2201 MAN0: Potline Return - Line 2

27/08/2018 0:00

MAN2201 MAN0: Extended potline change to provide Meridian with capacity required to restore

reduction line.

29/08/2018 23:47

MAN2201 MAN0: Required to manage potline 2 restoration

30/08/2018 6:30

WGN0331: Required for system security (SIR)

30/08/2018 6:30

WGN0331: Required for system security (FIR)

This report was published by the Authority on 19 September 2018. For further inquiries please contact the Electricity Authority via email to marketoperations@ea.govt.nz.