Compliance plan for Wairoa DC DUML - October 2018

Deriving submission info	ormation		
Non-compliance	Description		
Audit Ref: 2.1 With: Clause 11(1) of	Under submission of approx. 2,191 kWh per annum has occurred due to incorrect wattage and ballasts applied.		
Schedule 15.3	Potential impact: Low		
	Actual impact: Low		
From: 01-Jun-18	Audit history: Once		
To: 26-Sep-18	Controls: Moderate		
	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as moderate as the processes used to calculate submission are sufficient to mitigate risk most of the time.		
	The impact is assessed to be medium, above.	based on the kW	h differences described
Actions ta	ken to resolve the issue	Completion date	Remedial action status
Genesis has reviewed the information provided by Eastland and have found a formula error which is causing the 70w ballast to calculate 12 instead of 13 causing the 2076 kwh annual under submission. Genesis has contacted Eastland to have this amended.		01/12/2018	Identified
Genesis will be making amendments to the reconciliation data to cater for the historical settlement revisions			
Genesis has requested the 1 incorrect lamp responsible for the 115kwh annually, be corrected in the database.			
Preventative actions to	aken to ensure no further issues will occur	Completion date	
Genesis does analysis on data provided for streetlights and will continue to work alongside their customers to provide accurate information to the market.		01/12/2018	

Description and capacity			
Non-compliance	Description		
Audit Ref: 2.4	Gear wattage is not recorded in the database.		
With: Clause 11(2)(c)	Potential impact: Medium		
of Schedule 15.3	Actual impact: Low		
	Audit history: Once		
From: 01-Jun-18	Controls: Strong		
To: 26-Sep-18	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as strong because all items in the database have the lamp model and wattage recorded.		
	The impact on settlement is low beca gear wattages not being held in the c		as not been affected by
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis will liaise with Eastland to have this populated, genesis currently only receive a summary from Eastland, Genesis will request a detailed data set enabling verification of ballast amendments		01/03/2019	Investigating
Genesis will work with Eastland to have the ballast information populated accurately.		01/03/2019	

All load recorded in the database			
Non-compliance	Description		
Audit Ref: 2.5	One additional 27W LED lamp was discovered on Apatu Street.		
With: Clause 11(2A) of Schedule 15.3	Potential impact: Low Actual impact: Low		
From: 01-Jun-18	Audit history: None		
To: 26-Sep-18	Controls: Weak		
	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as weak, because updates to the database are only occurring due to "local knowledge" by Eastland staff, not through a formal update process. The impact is assessed to be low, based on the kWh differences described above.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis will need to speak with Eastland as to how they will progress with the tracking of changes.		01/06/2019	Investigating
Preventative actions taken to ensure no further issues will occur		Completion date	
Genesis will liaise with Eastland and track their progress with tracking of changes implementation.		01/06/2019	

Database accuracy			
Non-compliance	Description		
Audit Ref: 3.1 With: Clause 15.2 and	Under submission of approx. 151 kWh per annum has occurred due to one incorrect lamp wattage.		
15.37B(b)	Potential impact: Low		
	Actual impact: Low		
	Audit history: Once		
From: 01-Jun-18	Controls: Weak		
To: 26-Sep-18	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as weak, because updates to the database are only occurring due to "local knowledge" by Eastland staff, not through a formal update process. The impact is assessed to be low, based on the kWh differences described above.		
Actions taken to resolve the issue Completi		Completion date	Remedial action status
Genesis have requested Eastland to review this process, Genesis have yet to have a response from Eastland.		01/03/2019	Investigating
Preventative actions taken to ensure no further issues will occur		Completion date	
Genesis is reliant on the network to provide accurate information. Genesis will be working to ensure that Eastland implement a process that meets compliance.		01/03/2019	

Volume information accuracy			
Non-compliance	Description		
Audit Ref: 3.2 With: Clause 15.2 and	Under submission of approx. 2,191 kWh per annum has occurred due to incorrect wattage and ballasts applied.		
15.37B(c)	Potential impact: Low		
	Actual impact: Low		
	Audit history: Once		
From: 01-Apr-17	Controls: Moderate		
To: 26-Sep-18	Breach risk rating: 2		
Audit risk rating	Rationale fo	r audit risk rating	
Low	The controls are rated as moderate as the processes used to calculate submission are sufficient to mitigate risk most of the time. The impact is assessed to be low, based on the kWh differences described above.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis has informed Eastland that their calculation process for the ballast ratio is incorrect. Genesis has suggested that they change the "rounddown" function to "roundup" to avoid future reporting issues.		01/01/2019	Investigating
Preventative actions taken to ensure no further issues will occur		Completion date	
Genesis have request the actual detailed level information be reported alongside the summary currently being supplied. Genesis will however correct the ratio calculation if found to still be supplied in error. Genesis will also report any dataset issues once detailed level information starts to be supplied.		01/01/2019	