Compliance plan for NZTA Taupo DUML Audit 2018

Deriving submission information				
Non-compliance	Description			
Audit Ref: 2.1 With: Clause 11(1) of Schedule 15.3	Database extract used for submission is not up to date resulting in an estimated under submission of 5,452.25 kWh per annum. The field audit found one wattage discrepancy resulting in an estimated over submission of 358.76 kWh.			
	Potential impact: Low			
	Actual impact: Low			
From: unknown	Audit history: None			
	Controls: Weak			
To: 30-Apr-18	Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as weak as they are unlikely to mitigate risk and remove errors.			
	The impact is assessed to be low, based on the kWh differences.			
Actions taken to resolve the issue		Completion date	Remedial action status	
TRUS will work with Opus to review and correct the database Monthly reporting to TRUS to be set up		31/10/18 31/10/18	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Maintenance and validation processes to be reviewed.		31/10/18		

Tracking of load changes				
Non-compliance	Description			
Audit Ref: 2.6 With: Clause 11(3) of Schedule 15.3	Monthly reports not provided regularly. Tracking of load changes not provided by the existing contractor Potential impact: Low Actual impact: Low			
From: unknown To: 30-Apr-18	Audit history: None Controls: Weak Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as weak, as the changes are not well tracked, and regular monthly reports are not provided, but I note that this is expected to be rectified with the appointment of a new field contractor. The impact is assessed to be low, as the volume lights associated with this load is small.			
Actions taken to resolve the issue		Completion date	Remedial action status	
TRUS will follow up with Opus to ensure all updates are provided monthly		31/10/18	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Opus have a new contractor and expect that updates will be entered into RAMM going forward		Ongoing		

Database accuracy			
Non-compliance	Description		
Audit Ref: 3.1 With: Clause 15.2 and	The field audit found one wattage discrepancy resulting in an estimated over submission of 358.76 kWh.		
15.37B(b)	Potential impact: Low		
	Actual impact: Low		
	Audit history: None		
From: unknown	Controls: Weak		
To: 30-Apr-18	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as weak as they are unlikely to mitigate risk and remove errors. The impact is assessed to be low, based on the kWh differences described		
Actions taken to resolve the issue Completion Remedial act		Remedial action status	
Actions taken to resolve the issue		date	
TRUS will work with Opus to correct any database anomalies		31/10/18	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Opus have a new contractor and expect that updates will be entered into RAMM going forward		Ongoing	

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	Database extract used for submission is not up to date resulting in an estimated under submission of 5,452.25 kWh per annum. The field audit found one wattage discrepancy resulting in an estimated over submission of 358.76 kWh.			
	Potential impact: Low			
	Actual impact: Low			
	Audit history: None			
From: unknown	Controls: Weak			
To: 30-Apr-18	Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as weak as they are unlikely to mitigate risk and remove errors. The impact is assessed to be low, based on the kWh differences.			
Actions taken to resolve the issue		Completion date	Remedial action status	
TRUS will follow up with Opus to ensure all updates are provided monthly		31/10/18	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Opus have a new contractor and expect that updates will be entered into RAMM going forward		Ongoing		