## Compliance plan for Waipa Networks Limited-2018

Requirement to provide complete and accurate information			
Non-compliance	Description		
Audit Ref: 2.1	Registry information not complete and accurate in all instances.		
With: Clauses 11.2(1)			
and 10.6(1)	Actual impact: Low		
	Audit history: None		
From: 01-Jul-17	Controls: Moderate		
To: 30-Jun-18	Breach risk rating: 2		
Audit risk rating	Rationale fo	r audit risk rating	1
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur.		
	The risk rating is low as the discrepancies found have no direct impact on reconciliation.		o direct impact on
Actions taken to resolve the issue		Completion date	Remedial action status
Our additional checks along with additional resource we are committing to the process will result in general improvement in this area,		1/10/18	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
As above.		1/10/18	

Requirement to correct errors			
Non-compliance	Description		
Audit Ref: 2.2	Errors not corrected as soon as practicable.		
With: Clauses 11.2(2)	Potential impact: Low		
and 10.6(2)	Actual impact: Low		
	Audit history: None		
From: 01-Jul-17	Controls: Moderate		
To: 30-Jun-18	Breach risk rating: 2		
Audit risk rating	Rationale fo	or audit risk rating	<u>.</u>
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur.		
	The risk rating is low as the corrections not actioned have no direct impact on reconciliation.		
Actions taken to resolve the issue		Completion date	Remedial action status
Our additional checks along with additional resource we are committing to the process will result in general improvement in this area.		1/10/18	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
As above.		01/10/18	

Timeliness of Provision of ICP Information to the registry manager			
Non-compliance	Description		
Audit Ref: 3.4 With: Clause 7(2) of	16 ICPs not updated prior to electricity being traded. Potential impact: Low		
schedule 11.1	Actual impact: Low Audit history: None		
From: 10-Jul-17 To: 30-Jun-18	Controls: Strong Breach risk rating: 1		
Audit risk rating	Rationale fo	r audit risk rating	
Low	Controls are rated as strong as ICPs are being updated on the correct day. The error is occurring due to a file time processing issue. The risk rating is low as the volume of ICPs affected is small and the delay is one day in all instances.		
Actions taken to resolve the issue		Completion date	Remedial action status
This has now been corrected.		25/07/18	Cleared
Preventative actions ta	Preventative actions taken to ensure no further issues will occur		
As above.		25/07/18	

Timeliness of Provision of Initial Electrical Connection Date			
Non-compliance	Description		
Audit Ref: 3.5	31 initial electrical connection dates not updated within ten business days.		
With: Clause 7(2A) of	Potential impact: Low		
schedule 11.1	Actual impact: Low		
	Audit history: Once		
From: 10-Jul-17	Controls: Moderate		
To: 30-Jun-18	Breach risk rating: 2		
Audit risk rating	Rationale fo	r audit risk rating	
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur. The risk rating is low this has no direct impact on reconciliation.		
Actions taken to resolve the issue		Completion date	Remedial action status
We will add checks of the initial livening date and associated information.		1 October 2018	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
As above		1 October 2018	

Connection of an ICP that is not an NSP			
Non-compliance	Description		
Audit Ref: 3.6 With: Clause 11.17	16 ICPs connected before a trader was recorded on the registry as accepting responsibility. Potential impact: Low		
From: 01-Jul-17 To: 30-Jun-18	Actual impact: Low Audit history: None		
Controls: Moderate Breach risk rating: 2			
Audit risk rating	Rationale fo	r audit risk rating	
Low	Controls are rated as moderate ICPs are being updated on the correct day. The error is occurring due to a file time processing issue. The risk rating is low as the volume of ICPs affected is small and the delay is one day in all instances.		
Actions taken to resolve the issue		Completion date	Remedial action status
We have modified our system so the file is submitted to the Registry on the same day as the change.		25/07/18	Cleared
Preventative actions taken to ensure no further issues will occur		Completion date	
As above		25/07/18	

Changes to registry			
Non-compliance	Description		
Audit Ref: 4.1	Some price, network, status, and address changes were backdated.		
With: Clause 8	Potential impact: Low		
Schedule 11.1	Actual impact: Low		
	Audit history: Multiple		
From: 01-Apr-99	Controls: Moderate		
To: 30-Jun-18	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur. The risk rating is low as these events have no direct impact on reconciliation.		
		Completion date	Remedial action status
We will continue to backdate to fix errors but have also modified our process re decommissions as above.		30/07/18	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
As above		30/07/18	

ICP address readily locatable				
Non-compliance	Description			
Audit Ref: 4.4	69 ICPs with addresses that are not readily locatable.			
With: Clause 2	Potential impact: Low			
Schedule 11.1	Actual impact: Low			
	Audit history: Multiple			
From: 01-Apr-99	Controls: Moderate			
To: 30-Jun-18	Breach risk rating: 2			
Audit risk rating	Rationale fo	or audit risk rating	5	
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur.			
	The risk rating is low as this has no direct impact on reconciliation.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Our database does not allow the uniqueness of an address to be automatically checked however we have improved our manual checks and rechecks to reduce the number of duplicates. We also periodically contact Retailers for information where we don't have a readily locatable address but will do this more frequently as part of our checks.		01/10/18	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
As above.		01/10/18	]	

Distributors to Provide ICP Information to the Registry manager				
Non-compliance	Description			
Audit Ref: 4.6	Distributed generation details incorrect or missing			
With: Clause 7(1)	4 ICPs with the initial electrical connect	ction date missing		
Schedule 11.1	8 ICPs with an incorrect initial electric	8 ICPs with an incorrect initial electrical connection date populated.		
	5 ICPs with incorrect UML load record	led.		
From: 01-Jul-17	Potential impact: Low			
To: 30-Jun-18	Actual impact: Low			
	Audit history: Multiple			
	Controls: Moderate			
	Breach risk rating: 2			
Audit risk rating	Rationale fo	or audit risk rating		
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur.			
	The risk rating is low as this has no dir	ect impact on rec	onciliation.	
Actions taken to resolve the issue		Completion date	Remedial action status	
We have corrected the L	INM load errors as above.	25/07/18	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
We will have our systems person look at whether or not the output field for the UNM can be modified to the registry standard and if not then a flag generated when the UNM load price category is input alerting the user to enter the required format manually. Re the input errors – these will happen, but our improved reporting and checks should pick these up sooner.		01/10/18		

Management of "decommissioned" status			
Non-compliance	Description		
Audit Ref: 4.11	Eight ICPs decommissioned but not updated on the registry.		
With: Clause 20	Potential impact: Low		
Schedule 11.1	Actual impact: Low		
	Audit history: None		
From: 28-Aug-17	Controls: Moderate		
To: 30-Jun-18	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as moderate as they will mitigate risk most of the time but there is room for errors to occur. The risk rating is low as this has no direct impact on reconciliation.		
Actions taken to resolve the issue		Completion date	Remedial action status
The changes to our process to update these in MagiQ at the time of physical decommissioning will ensure discrepancies are picked up in our regular checks.		25/07/18	Identified
Preventative actions ta	aken to ensure no further issues will occur	Completion date	
As above		25/07/18	