Compliance plan for Hastings DC DUML – 2018

Deriving submission information					
Non-compliance	Description				
Audit Ref: 2.1 With: Clause 11(1) of Schedule 15.3	Incorrect ballasts applied resulting in an estimated 13,796.7 kWh under submission. 14 records have blank or unknown lamp wattages, leading to over submission o				
	approximately 16,828 kWh per annum.				
From: 01-Feb-17	Potential impact: Medium				
To: 24-Sep-18	Actual impact: Medium				
	Audit history: Once				
	Controls: Moderate				
	Breach risk rating: 4				
Audit risk rating	Rationale fo	r audit risk rating	5		
Medium	The controls are rated as moderate, because they are sufficient to ensure that lamp information is correctly recorded most of the time, but there are still some errors. The impact is assessed to be medium, based on the kWh differences described above.				
Actions taken to resolve the issue		Completion date	Remedial action status		
Genesis analysed the detailed data being provided to Genesis. Genesis has found the only blank/zero listed lamp items are in fact for driver feedback signs and pay and display chargers listed in the database. Genesis have sent HDC the dataset error and have requested these to be amended.		01/03/2019	Identified		
Genesis has analysed the process of deriving the total kWh's and has found that it rounds up the value as its rounded to 2 decimal places. Genesis are investigating whether Gentrack can accept decimal places greater than 2 in the TOU billing module.					
Preventative actions taken to ensure no further issues will occur		Completion date			
Genesis analyses the data each month feedback any erroneous data and make the necessary changes for settlements/billing processes.		01/03/2019			

Description and capacity of load				
Non-compliance	Description			
Audit Ref: 2.4 With: Clause 11(2)(c) of Schedule 15.3	14 records with blank or 'unknown' lamp description and missing wattage values. Potential impact: Medium Actual impact: Medium			
From: 01-Feb-17	Audit history: Once			
To: 24-Sep-18	Controls: Moderate			
	Breach risk rating: 4			
Audit risk rating	Rationale for audit risk rating			
Medium	The controls are recorded as moderate because there is room for improvement.			
	The audit risk rating is medium due to the estimated over submission by approximately 16,828 kWh per annum.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis analyzed the detailed data being provided to Genesis. Genesis has found the only blank/zero listed lamp items are in fact for driver feedback signs and pay and display chargers listed in the database. Genesis have sent HDC the dataset error and have requested these to be amended.		01/03/2019	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis analyses the data each month feedback any erroneous data and make the necessary changes for settlements/billing processes.		01/03/2019		

Database accuracy				
Non-compliance	Description			
Audit Ref: 3.1 With: Clause 15.2 and	14 records have blank or unknown lamp wattages, leading to over submission of approximately 16,828 kWh per annum.			
15.37B(b)	Incorrect ballasts applied resulting in a submission.	an estimated 13,796.7 kWh under		
From: 01-Feb-17	92 metered lamps recorded incorrectly against an unmetered ICP.			
To: 24-Sep-18	Potential impact: High			
	Actual impact: Medium			
	Audit history: Once			
	Controls: Moderate			
	Breach risk rating: 4			
Audit risk rating	Rationale for audit risk rating			
Medium	The controls are rated as moderate, because they are sufficient to ensure the database is accurate most of the time. The impact is assessed to be medium, based on the kWh differences described above.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis analysed the detailed data being provided to Genesis. Genesis has found the only blank/zero listed lamp items are in fact for driver feedback signs and pay and display chargers listed in the database. Genesis have sent HDC the dataset error and have requested these to be amended.		01/03/2019	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis analyses the data each month feedback any erroneous data and make the necessary changes for settlements/billing processes.		01/03/2019		

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	Submission calculation difference leading to a 3 kWh over submission for the month of September. Incorrect ballasts applied resulting in an estimated 13,796.7 kWh under submission.			
From: 01-Feb-17	14 records have blank or unknown lamp wattages, leading to over submission of approximately 16,828 kWh per annum.			
To: 24-Sep-18	Potential impact: High			
	Actual impact: Medium			
	Audit history: Once			
	Controls: Moderate			
	Breach risk rating: 4			
Audit risk rating	Rationale fo	r audit risk rating	5	
Medium	The controls are rated as moderate, because they are sufficient to ensure that lamp information is correctly recorded most of the time but there are still some errors. The impact is assessed to be medium, based on the kWh differences described above.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis the findings regarding the logger variation, as the same logger is used with Napier CC and there was no issue recorded against 3.2 in relation to the logger 206562019.		01/03/2019	Investigating	
Genesis analysed the detailed data being provided to Genesis. Genesis has found the only blank/zero listed lamp items are in fact for driver feedback signs and pay and display chargers listed in the database. Genesis have sent HDC the dataset error and have requested these to be amended.				
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis analyses the data each month feedback any erroneous data and make the necessary changes for settlements/billing processes.		01/03/2019		