Compliance plan for Waikato DC DUML –November 2018

Deriving submission information					
Non-compliance	Description				
Audit Ref: 2.1 With: Clause 11(1) of Schedule 15.3	Analysis of the database found 13 lamps with the incorrect LED wattage recorded indicating an estimated minor under submission of 713 kWh per annum.				
2011044110 2010	Potential impact: Medium				
	Actual impact: Low				
From: 01-May-18	Audit history: None				
To: 31-Oct-18	Controls: Moderate				
	Breach risk rating: 2				
Audit risk rating	Rationale for audit risk rating				
Low	The controls are rated as moderate as the processes in place to manage change are sufficient to mitigate risk most of the time. The impact is assessed to be medium, based on the kWh differences.				
Actions taken to resolve the issue		Completion date	Remedial action status		
Genesis will work with Odyssey Energy Ltd to ascertain the correct lamp wattages for the 13 assets.		01/03/2019	Identified		
Preventative actions taken to ensure no further issues will occur		Completion date			
Genesis will be recommending a review of the tracking of load changes to ensure the correct information is being provided and updated in a timely manner		01/03/2019			

All load recorded in database				
Non-compliance	Description			
Audit Ref: 2.5	Two items of load are missing from the database.			
With: Clause 11(2A) of	Potential impact: Medium			
Schedule 15.3	Actual impact: Low			
	Audit history: Once previously			
From: 01-May-18	Controls: Moderate			
To: 31-Oct-18	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as moderate as the processes in place to manage change are sufficient to mitigate risk most of the time.			
	The impact is assessed to be low, based on the database accuracy as detailed in section 3.1.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis will work with Odyssey Energy Ltd to ascertain the correct lamp wattages for the 13 assets.		01/03/2019	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis will be recommending a review of the tracking of load changes to ensure the correct information is being provided and updated in a timely manner		01/03/2019		

Database accuracy				
Non-compliance	Description			
Audit Ref: 3.1 With: Clause 15.2 and 15.37B(b)	Analysis of the database found 13 lamps with the incorrect LED wattage recorded indicating an estimated minor under submission of 713 kWh per annum.			
	Potential impact: Medium			
	Actual impact: Low			
From: 01-May-18 To: 31-Oct-18	Audit history: Once previously			
	Controls: Moderate			
	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as moderate as the processes in place to manage change are sufficient to mitigate risk most of the time.			
	The impact is assessed to be low, based on the kWh value above.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis will work with Odyssey Energy Ltd to ascertain the correct lamp wattages for the 13 assets. O1/03/2019 Identified			Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis will be recommending a review of the tracking of load changes to ensure the correct information is being provided and updated in a timely manner		01/03/2019		

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	Analysis of the database found 13 lamps with the incorrect LED wattage recorded indicating an estimated minor under submission of 713 kWh per annum.			
20.07 2(0)	Potential impact: Medium			
	Actual impact: Low			
From: 01-May-18	Audit history: Once previously			
To: 31-Oct-18	Controls: Moderate			
	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as moderate as the processes in place to manage change are sufficient to mitigate risk most of the time. The impact is assessed to be low, based on the kWh value above.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis will work with Odyssey Energy Ltd to ascertain the correct lamp wattages for the 13 assets.		01/03/2019	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Genesis will be recommending a review of the tracking of load changes to ensure the correct information is being provided and updated in a timely manner		01/03/2019		