Compliance plan for Oyster Network Limited Distributor audit – 2021

Timeliness of Provision of Initial Electrical Connection Date				
Non-compliance	Description			
Audit Ref: 3.5	12 ICPs Initial Electrical Connection dates updated late.			
With: 7(2A) of	Potential impact: None			
Schedule 11.1	Actual impact: None			
	Audit history: Multiple			
From: 01-Sep-19	Controls: Moderate			
To: 31-Dec-20	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as moderate - checks are in place to monitor changes to active.			
	This has no direct impact on submission hence the audit risk rating is low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
This is an ongoing issue for us and (we understand) other participants. It is disappointing and frustrating that our level of compliance in this area remains similar (~85%) to the last audit. Our processes as they stand are generally working but clearly are not 100% where other parties are slow to provide details. At this stage we are reviewing how some of the local networks combat the issue but other than measures mentioned in previous audit reports, we unfortunately don't have any specific new actions to report at this time.		ongoing	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
As above		ongoing		

Changes to Registry information				
Non-compliance	Description			
Audit Ref: 4.1	One backdated pricing event.			
With: 8 Schedule 11.1	Three late updates to decommissioned.			
	Potential impact: Low			
	Actual impact: Low			
	Audit history: Twice previously			
From: 01-Jan-19	Controls: Strong			
To: 31-Dec-20	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as strong - checks are in place to monitor registry changes.			
	This affected four ICPs therefore the audit risk rating is low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
As noted above controls in this area are strong. Decommissioning events can sometimes cause issues due to communication and understanding between trader and distributor particularly concerning temporary ICPs. Updates were made as soon as we became aware of changes/actions.		ongoing	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
We will continue to pay close attention to status changes so that we can react quickly enough to remain compliant.		ongoing		