## Compliance Plan for Network Waitaki MEP – March 2022

Changes to Registry Records				
Non-compliance	Description			
Audit Ref: 4.10	Some records updated on the registry later than 10 business days.			
With: Clause 3 of Potential impact: Low				
Schedule 11.4	Actual impact: Low			
	Audit history: Multiple times			
From: 01-May-20	Controls: Strong			
To: 10-Feb-22	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	I have recorded the controls as strong as Network Waitaki had updated its processes regarding the bulk updates following statistical recertification.			
	The impact on participants, customers or settlement could be minor where a certification update is late; therefore, the audit risk rating is low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Investigated why the updates were late and the effectiveness of our controls.		31/03/22	Cleared	
Preventative actions taken to ensure no further issues will occur		Completion date		
After our review of controls, we updated our processes to prevent this happening again.		31/03/22		
Refer to files:				
05 Replace and Test a Sample of Meters at 15 Years – Process				
04 10 Year Meter Inspections process				

Accurate and Complete Records			
Non-compliance	Description		
Audit Ref: 5.1 With: Clause 4(1) of	Some incomplete certification records	i.	
Schedule 10.6	Potential impact: Low		
	Actual impact: Low		
From: 01-May-20	Audit history: None		
To: 10-Feb-22	Controls: Strong		
	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	I have recorded the controls strong as Network Waitaki had updated certification report template used by its inspectors to include all test results, before this this audit report was finalised.  There is a minor impact on other participants; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
We have reviewed the causes of the incomplete records and checked our controls for effectiveness		31/3/22	Cleared
Preventative actions taken to ensure no further issues will occur		Completion date	
Form amended by Metering Team and forms will be checked for completeness when received.		31/3/22	
Refer file: 03 NWL Job Sh	neet v3.0 28Mar2022.pdf		

Provision of Registry Information					
Non-compliance	Description				
Audit Ref: 6.2	Small number of registry discrepancies.				
With: Clause 7 (1), (2)	Potential impact: Low				
and (3) of Schedule	Actual impact: Low				
11.4	Audit history: Multiple times				
From: 01-May-20	Controls: Strong				
To: 10-Feb-22	Breach risk rating: 1				
Audit risk rating	Rationale for audit risk rating				
Low	I have recorded the controls as strong in this area because there were only a small number of issues, most of which are now resolved.				
	Very few of the discrepancies have an impact on participants, customers or settlement. The audit risk rating is low.				
Actions taken to resolve the issue		Completion date	Remedial action status		
WE have amended the incorrect ATH identifier and have been removed by Meridian as MEP for the Benmore Dam supply and have confirmed that the ANSIC codes are correct for the CN only ICPs		31/3/22	Cleared		
Preventative actions taken to ensure no further issues will occur		Completion date			
We have received a proposal for review of our data checking scripts to identify any other automated checking we can do to avoid these errors reoccurring. We plan to review this over the next 2 months.		31/3/22			

Cancellation of Certification			
Non-compliance	Description		
Audit Ref: 6.4 With: Clause 6 of Schedule 11.4 From: 01-May-20 To: 10-Mar-22	Certification cancelled, and registry not updated for:  - 12 Category 1 ICPs not inspected within maximum inspection period, and - one Cat 2 ICP certified with low burden.  Potential impact: Low  Actual impact: Low  Audit history: None  Controls: Strong  Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	I have recorded the controls as strong as Network Waitaki has a regime in place and the missed and late inspections were due to access issues.  It is unlikely that the missed inspections will impact on other participants and on settlement. The audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Certification has been cancelled for these ICPs.		30/3/22	Cleared
Cat 2 metering replaced with Cat 1 metering.			
Preventative actions taken to ensure no further issues will occur		Completion date	
We have amended our process to make it clear that certification must be cancelled if not inspected by the due date.		31/3/22	

Certification and Maintenance			
Non-compliance	Description		
Audit Ref: 7.1	Certification cancelled for:		
With: Clause 10.38 (a),	- 12 Category 1 ICPs not inspected within maximum inspection period, and		
clause 1 and clause 15 of Schedule 10.7	- one Cat 2 ICP certified with low burden.		
From: 05-Jan-20	Potential impact: High		
To: 06-Mar-20	Actual impact: Low		
	Audit history: Multiple times		
	Controls: Strong		
	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	I have recorded the controls as strong because Network Waitaki has a good process in place to identify and recertify installations.		
	The impact on settlement is recorded as low. The likelihood of failure or inaccuracy for metering installations with expired certification is low based on the age and type of meters and previous calibration results for these meters.		
Actions taken to resolve the issue		Completion date	Remedial action status
We have cancelled certification for these meters and included them in the 2022 stat sample group which we are aiming to have recertified by June 2022		31/3/22	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
We have amended our 10 year inspection process to make it clear of the requirements for inspecting within 10.5 year timeframe.		31/3/22	

Category 1 Inspections			
Non-compliance	Description		
Audit Ref: 8.1 With: Clause 45 of Schedule 10.7	12 Category 1 metering installations no inspection period. Potential impact: Low Actual impact: Low	ot inspected with	in the maximum
From: 05-Sep-20 To: 11-Jul-21	Audit history: Once Controls: Strong Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	I have recorded the controls as strong as Network Waitaki has a regime in place and only 12 inspections were not conducted within the maximum inspection period due to access issues.  It is unlikely that the missed inspections will impact on other participants and on settlement. The audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
We have cancelled certification for these meters and included them in the 2022 stat sample group which we are aiming to have recertified by June 2022		31/3/22	Cleared
Preventative actions taken to ensure no further issues will occur		Completion date	
We have amended our 10 year inspection process to make it clear of the requirements for inspecting within 10.5 year timeframe.		31/3/22	