

Report on market operation service providers' compliance

March 2018

This report includes:

- the publication¹ of the sections of the reports that relate to breaches of the Electricity Industry Participation Code (Code) by the pricing manager, received by the Authority in the previous calendar month
- the republication² of the sections of the reports that relate to breaches of the Code by the clearing manager, received by the Authority in the previous calendar month
- the republication³ of the sections of the initial report that relate to breaches of the Code by the reconciliation manager, received by the Authority in the current calendar month
- the republication of the sections of the report that relate to breaches of the Code by the FTR manager, received by the Authority during the previous calendar month
- the republication of the sections of the report that relate to breaches of the Code by the registry manager, received by the Authority during the current calendar month
- the republication of sections of the report that relate to breaches of the Code by the system operator and the system operator's discretionary action, received by the Authority in the previous month.

¹ As required by clause 13.214 of the Code

² As required by clause 14.69 of the Code

³ Clause 15.33 of the Code requires the Authority to publish the sections of the reports that relate to an alleged breach of the Code by the reconciliation manager by 1630 hours on the 2nd business day following the day on which the Authority receives the report. These reports are available at <u>http://www.ea.govt.nz/industry/market/statistics-reports/reconciliationmanager-monthly-breach-reports/</u>.

Self-reported breaches by the pricing manager (under clause 13.213 of the Code)

There were no self-reported breaches by the pricing manager.

Self-reported breaches by the clearing manager (under clause 14.68 of the Code)

There were no self-reported breaches by the clearing manager.

Self-reported breaches by the reconciliation manager *(under clause 15.30(1) of the Code)* Note that this is a summary of the reconciliation manager monthly breach report which is published separately

There were no self-reported breaches by the reconciliation manager.

Self-reported breaches by the FTR manager (Not required by the Code)

There were no self-reported breaches by the FTR manager.

Self-reported breaches by the registry manager (Not required by the Code)

There were no self-reported breaches by the registry manager.

Self-reported breaches by the system operator (under clause 3.14)

There were no self-reported breaches by the system operator.

Discretionary action by the system operator (under clause 13.102)

Event Date & Time Event Description

01-02-2018 01:09 p.m. TUI1101 PRI0 Discretion ended for return of RDF WRK 1

01-02-2018 01:09 p.m. TUI1101 PRI0 Discretion ended for return of RDF WRK 1

01-02-2018 01:12 p.m. TUI1101 PRI0 Discretion ended for return of RDF WRK 1

09-02-2018 05:06 a.m. SFD2201 SPL0 Bona-fide change to offer claimed

Discretionary action by the system operator (under clause 13.102)

14-02-2018 06:21 a.m. ARG1101 BRR0 Required off for switching ARG_BLN
15-02-2018 02:00 p.m. ARG1101 BRR0 Required off for switching ARG_BLN
19-02-2018 06:18 a.m. ARG1101 BRR0 Required off for switching ARG-KIK-1
19-02-2018 03:58 p.m. ARG1101 BRR0 Required off for switching ARG-KIK-1
20-02-2018 04:16 p.m. KPA1101 KPI1 KPI islanded upon OPK_KPI_SFD_2 tripping
21-02-2018 02:24 a.m. COL0661 COL0 Discretion on to provide upper south island MVAr support
21-02-2018 02:27 a.m. COL0661 COL0 Discretion on to provide upper south island MVAr support
21-02-2018 03:42 a.m. COL0661 COL0 Discretion on to provide upper south island MVAr support
26-02-2018 07:29 a.m. ARG1101 BRR0 Required off for switching ARG-KIK-1
27-02-2018 09:55 p.m. MAN2201 MAN0 Required for extension of emergency potline

This report was published by the Authority on 21 March 2018. For further inquiries please contact the Electricity Authority via email to <u>marketoperations@ea.govt.nz</u>.