Compliance plan for Ecosmart - 2019

Non-compliance	Description			
Audit Ref: 3.3	Two updates to the registry were later than five business days			
With: 10 of Schedule	Potential impact: Low			
11.1	Actual impact: Low			
	Audit history: Twice previously			
From: 17-Jan-19	Controls: Strong			
To: 04-May-19	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are recorded as strong, there are is a solid process in place. There are not many activities happening in the registry, which requires even more vigilance to meet compliance with this clause. The audit risk rating is low because there is minor impact on the settlement outcome.			
Actions taken to resolve the issue		Completion date	Remedial action status	
			Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Some backdated updates are inevitable to maintain accuracy no remedial action planned				

Non-compliance	Description			
Audit Ref: 4.3	One CS file was late by one day			
With: 5 of Schedule	Potential impact: Low			
11.3	Actual impact: Low			
	Audit history: None			
From: 21-Dec-18	Controls: Strong			
To: 05-Jan-19	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are recorded as strong, there is a robust process in place. As soon as a notification from the registry is sent, Ecosmart is automatically alerted. There are not many switching activities therefore even more vigilance is required to meet compliance with this clause. The audit risk rating is low because there is minor impact on the settlement outcome.			
Actions taken to resolve the issue		Completion date	Remedial action status	
			Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Systems are already in place				

My software now notifies me of switch breaches.

So now these are usually done the same day of the switch breach notice.

This problem should never occur again.

Non-compliance	Description			
Audit Ref: 11.3 With: 15.7	Energy supplied is calculated by JC Consulting from the previous months Initial Network volumes			
vvicii. 13./	Potential impact: None			
From: 01-Aug-18 To: 20-Jun-19	Actual impact: Low			
	Audit history: None			
	Controls: Moderate			
	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are recorded as moderate because data is not coming from a billing system, however volumes submitted to networks are very accurate based on meter readings. There is no impact on settlement outcomes. Audit risk low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
This has now been remedied to come from ECOS billing software instead of from John Candy's submitted vols.			Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
A scheduled automatic task has been created to submit the file at the beginning of each month.				

Non-compliance	Description		
Audit Ref: 11.4	HHRAGGR files do not contain electricity supplied information		
With: 15.8	Potential impact: Low		
	Actual impact: Low		
From: 01-Aug-18	Audit history: None		
To: 30-Jun-19	Controls: Strong		
	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Ecosmart submits submissions volumes as per the reconciliation manager specification.		
Actions taken to resolve the issue		Completion date	Remedial action status
			Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
NO remedial action from ECOS is planned			