



NZX Limited
Level 1, NZX Centre
11 Cable Street
PO Box 2959
Wellington 6140
New Zealand
Tel +64 4 472 7599

www.nzx.com

13 September 2018

Electricity Authority Board
P O Box 10041
Wellington

Dear Sir/Madam,

Reconciliation manager's breach report for September 2018

The reconciliation manager advises, in accordance with Clause 15.4(1) of the Electricity Industry Participation Code 2010, alleged breaches of the Code for August 2018 initial.

Breaches by reconciliation manager of the Code:

The Reconciliation Manager has failed to separate submission information using a profile to allocate the non-half hour submission information in breach of Part 15.19 (1) of the Code.

Breaches by reconciliation participants of the Code:

To our knowledge, there have been no alleged breaches by reconciliation participants.

Yours sincerely,

A handwritten signature in black ink, appearing to read 'Jason Lim'. The signature is fluid and cursive, with the first letter 'J' being particularly large and stylized.

Jason Lim
For and on behalf of
The reconciliation manager