



NZX Limited
Level 1, NZX Centre
11 Cable Street
PO Box 2959
Wellington 6140
New Zealand
Tel +64 4 472 7599

www.nzx.com

11 October 2018

Electricity Authority Board
P O Box 10041
Wellington

Dear Sir/Madam,

Reconciliation manager's breach report for October 2018

The reconciliation manager advises, in accordance with Clause 15.4(1) of the Electricity Industry Participation Code 2010, alleged breaches of the Code for October 2018 initial.

Breaches by reconciliation manager of the Code:

The reconciliation manager has failed to reconcile submission information using the latest profile shape published in breach of Part 15.19 of the Code.

Breaches by reconciliation participants of the Code:

Two participants failed to submit data by 16:00 on business day 4 in breach of Part 15.4 (1) of the Code.

One participant failed to submit data by 16:00 on business day 4 in breach of Part 15.2 (1) of the Code.

Yours sincerely,

A handwritten signature in black ink, appearing to read 'Jason'.

Jason Lim
For and on behalf of
The reconciliation manager