Compliance plan for Wellington Advertising Signs – 2019

| Distributed unmetered load audits | | | |
|--|---|-------------------------|------------------------|
| Non-compliance | Description | | |
| Audit Ref: 1.10 | Audit conducted late for database | | |
| With: Clause 16A.26 | Potential impact: Medium | | |
| and 17.295F | Actual impact: Low | | |
| | Audit history: None | | |
| From: 01-Jun-18 | Controls: Moderate | | |
| To: 31-Jul-19 Breach risk rating: 2 | | | |
| Audit risk rating | Rationale for audit risk rating | | |
| Low | The controls are recorded as moderate based on the controls in place now, which will ensure ongoing audits will be conducted. Prime wanted to ensure the data was 100% accurate before having an audit conducted. The impact on settlement and participants is minor; therefore the audit risk | | |
| | rating is low. | | |
| Actions taken to resolve the issue | | Completion date | Remedial action status |
| The list was inherited by Wellington Electricity as a bucket list from GENE/VECT during the change over back in 2008 so we had to ensure the signs existed | | June 2019 | Cleared |
| Preventative actions taken to ensure no further issues will occur | | Completion date | |
| Now that we have compiled the 1 st database & have all the photos/spec from the customer. It will be easier to monitor the changes in the future. We will also inform the network to update their record. We hadn't done this because we wanted to ensure the database was audited prior to us requesting the network to make any changes.] | | Proposed or actual date | |